

CERTIFICATE OF ANALYSIS

FIBRE IDENTIFICATION REPORT

HSE Job No:	LJ.205164.SAa	Client Reference:	-
Report No:	LJ.205164.SAa – 3FI	Date Received:	14/03/16
Client:	Macca's Demolition & Asbestos Removal		
Client Address:	105 – 111 Bowen Street, Echuca Vic		
Sampled By:	As received		
Location:	5800 Cobb Hwy, Deniliquin NSW		
Analysis Method:	Samples analysed by Polarized Light Microscopy (PLM) techniques and Dispersion Staining (DS) using AS 4964-2004 and Health Safety Environment Australia SWI 04.		

Sample Number	Sample Description (approximate dimensions)	Analysis Results
Sample 1	Ceiling on Third Floor Fibre Cement Sheet (80 x 55 x 5mm)	No Asbestos Detected Organic Fibres Detected



Accreditation No: 15696

Accredited for compliance with ISO/IEC 17025



Approved Identifier
Sheree Brumler
17/03/2016

This test report shall not be reproduced except in full.