

P & DA CARUSO

BARHAM ROAD

PO BOX 373

DENILQUIN NSW 2710

Phone: (03) 5881 4435 Fax: (03) 5881 3545

Mobile: 0427 585 791

Tax Invoice

A.B.N. 18 517 965 875

A.C.N.

Invoice #: 00022917

Date: 2/02/2023

Ship Via:

Page: 1

ARC AUTHORISATION NO. AU11252

MOTOR VEHICLE REPAIRER NO. MVRL25484

Bill To:

Ship To:

DOWN TO EARTH VIC CO-OP SOC

P O BOX 295

BRUNSWICK EAST VIC 3057

DOWN TO EARTH VIC CO-OP SOC

P O BOX 295

BRUNSWICK EAST VIC 3057

Description

Amount Code

REPAIRS TO GREAT WALL UTE

CHECK OVER GREAT WALL.START AND RUN FOUND MISSFIRE.REMOVE TIMING
COVER WILL HAVE TO DISMANTLE MORE TO CHECK TIMING. DTE TO PICK UP UTE.

\$137.50 GST

Your Order #:

Customer ABN:

Shipping Date:

Terms: Net 30th after

Freight:

\$0.00 GST

COMMENT

CODE

RATE

GST

SALE AMOUNT

GST:

\$13.75

GST

10%

\$13.75

\$137.50

Total Inc GST:

\$151.25

Amount Applied:

\$0.00

Balance Due:

\$151.25

ANZ Bank Account Details:

Name: P & DA Caruso

BSB: 012 605 Account No: 439840612